

Briefing Note		DATE: 21/08/2024
		ISSUE: 01
		PAGE: Page 1 of 1
No: BN-185	Title: Certisecure Electric Strikes	APPROVED: P. Brash



Following some unexpected test results on Certisecure doorsets fitted with electric strikes the decision has been reluctantly made to withdraw them from our Certisecure certification until we can determine the root cause behind the test results.

All future orders for access control doorsets fitted with electric strikes **CANNOT** be offered as Certisecure products and should **NOT** be supplied with a Certisecure label affixed to the leaf head.

The decision to withdraw the product from Certisecure does **NOT** affect our Certifire certification. This product is remains compliant with our FD60 certification providing all the requirements are followed. Certifire labels should be affixed to the leaf head.

**Sales/Estimating/Contracts:** Do **NOT** offer electric strike access control products as Certisecure certificated items either verbally or in writing (including on any quotations)

**Planning:** Please ensure that Works Orders do **NOT** include a Certisecure label requirement for doorsets fitted with electric strikes

**Assembly:** Do **NOT** affix Certisecure labels to leaf heads on doorsets fitted with electric strikes. If you are not sure please ask